YASKAWA Electric Corporation High Speed Ethernet Server Driver

지원 버전 TOP Design Studio

V1.4.2 이상



CONTENTS

본 사 ㈜M2I의 "Touch Operation Panel(M2I TOP) Series"를 사용해주시는 고객님께 감사 드립니다. 본 매뉴얼을 읽고 "TOP-외부장치"의 접속방법 및 절차를 숙지해 주십시오.

1. 시스템 구성

2 페이지

접속에 필요한 기기, 각 기기의 설정, 케이블, 구성 가능한 시스템에 대해 설명합니다.

2. 외부 장치 선택

3 페이지

TOP 기종과 외부 장치를 선택합니다.

3. TOP 통신 설정

4 페이지

TOP 통신 설정 방법에 대해서 설명합니다.

4. 외부 장치 설정

10 페이지

외부 장치의 통신 설정 방법에 대해서 설명합니다.

5. 지원 어드레스

11 페이지

본 절을 참조하여 외부 장치와 통신 가능한 어드레스를 확인하십시오.



1. 시스템 구성

TOP와 "YASKAWA Electric Corp. - High Speed Ethernet Server" 의 시스템 구성은 아래와 같습니다.


시리즈	CPU	Link I/F	통신 방식	통신설정	케이블	
DX200	DX200	LAN port on the controller	Ethernet (UDP)		트위스트 페어	
DX100	DX100	LAN port on the controller	Ethernet (UDP)	2 TOD 통시 성정		
FS100	FS100	Ethernet port on the controller	Ethernet (UDP)	3. TOP 통신 설정 4. 외부 장치 설정	드위으로 페이 케이블* 주 1)	
DX200	DX200	LAN port on the controller	Ethernet (UDP)	<u> = </u>	" 12	
FS100L	FS100L	Ethernet port on the controller	Ethernet (UDP)			

*주1) 트위스트 페어 케이블


- STP(실드 트위스트 페어 케이블) 혹은 UTP(비실드 트위스트 페어 케이블) 카테고리 3, 4, 5 를 의미합니다.
- 네트워크 구성에 따라 허브, 트랜시버 등의 구성기기에 접속 가능하며 이 경우 다이렉트 케이블을 사용 하십시오.

■ 연결 가능 구성

·1:1 연결(TOP 1 대와 외부 장치 1 대) 연결



·1:N 연결(TOP 1 대와 외부 장치 여러 대) 연결





2. 외부 장치 선택

■ TOP 모델 및 포트 선택 후 외부 장치를 선택합니다.



설정 사항		내 용				
TOP	모델	TOP 디스플레이와 프로세스를 확인하여 터치 모델을 선택합니다.				
외부 장치	제조사	TOP와 연결할 외부 장치의 제조사를 선택합니다. "YASKAWA Electric Corporation"를 선택 하십시오.				
	PLC	TOP와 연결할 외부 장치를 선택합니다.				
		모델	인터페이스	프로토콜		
		High Speed Ethernet Server	Ethernet	High Speed Ethernet Server		
	의 시스템 구성에서 확인 하시기					



3. TOP 통신 설정

통신 설정은 TOP Design Studio 혹은 TOP 메인 메뉴에서 설정 가능 합니다. 통신 설정은 외부 장치와 동일하게 설정해야 합니다.

3.1 TOP Design Studio 에서 통신 설정

- (1) 통신 인터페이스 설정
 - [프로젝트 > 프로젝트 속성 > TOP 설정] → [프로젝트 옵션 > "HMI 설정 사용" 체크 > 편집 > 이더넷]
 - TOP 통신 인터페이스를 TOP Design Studio에서 설정합니다.





항 목	ТОР	외부 장치	비고
IP 주소*주1)주2)	192.168.255.50	192.168.255.1	
서브넷 마스크	255.255.255.0	255.255.255.0	
게이트 웨이	192.168.0.1	192.168.0.1	

^{*}주1) TOP와 외부 장치의 네트워크 주소 (IP 앞 세자리 192.168.0.0)는 일치해야 합니다.

[※] 위의 설정 내용은 본 사에서 권장하는 예제입니다.

항 목	설 명
IP 주소	네트워크 상에서 TOP가 사용 할 IP 주소를 설정합니다.
서브넷 마스크	네트워크의 서브넷 마스크를 입력합니다.
게이트 웨이	네트워크의 게이트 웨이를 입력합니다.




Default IP는 시리즈별 아래와 같습니다.

- DX100,200 시리즈: 192.168.255.1

- FS100 시리즈 : 10.0.0.2 - 포트번호 : 10040

(2) 통신 옵션 설정

- [프로젝트 > 프로젝트 속성 > PLC 설정 > ETHERNET > "PLC1 : High Speed Ethernet Server"]
 - High Speed Ethernet Server 통신 드라이버의 옵션을 TOP Design Studio에서 설정합니다.



^{*}주2) 동일 네트워크 상에서 중복된 IP 주소를 사용하지 마십시오.




항 목	설 정	비고
인터페이스	"Ethernet"을 선택합니다.	"2. 외부 장치
프로토콜	"High Speed Ethernet Server"을 선택합니다.	<u>선택" 참고</u>
IP	외부 장치의 IP 주소를 입력 합니다.	
Ethernet Protocol	TOP - 외부 장치 간 이더넷 프로토콜을 선택합니다.	
Port	외부 장치의 이더넷 통신 포트 번호를 입력합니다.	
TimeOut (ms)	TOP가 외부 장치로부터 응답을 기다리는 시간을 설정합니다.	
SendWait (ms)	TOP가 외부 장치로부터 응답 수신 후 다음 명령어 요청 전송 간에 대기 시간을	
	설정합니다.	



3.2 TOP 에서 통신 설정


※ "3.1 TOP Design Studio 에서 통신 설정" 항목의 "HMI 설정 사용"을 체크 하지 않은 경우의 설정 방법입니다.

■ TOP 화면 상단을 터치하여 아래로 <u>드래그</u> 합니다. 팝업 창의 "EXIT"를 터치하여 메인 화면으로 이동합니다.



(1) 통신 인터페이스 설정

■ [메인 화면 > 제어판 > 이더넷]



항 목	ТОР	외부 장치	비고
IP 주소*주1)주2)	192.168.255.50	192.168.255.1	
서브넷 마스크	255.255.255.0	255.255.255.0	
게이트 웨이	192.168.0.1	192.168.0.1	

^{*}주1) TOP와 외부 장치의 네트워크 주소 (IP 앞 세자리 <u>192.168.0</u>.0)는 일치해야 합니다.

[※] 위의 설정 내용은 본 사에서 권장하는 예제입니다.


항 목	설 명
IP 주소	네트워크 상에서 TOP가 사용 할 IP 주소를 설정합니다.
서브넷 마스크	네트워크의 서브넷 마스크를 입력합니다.
게이트 웨이	네트워크의 게이트 웨이를 입력합니다.

^{*}주2) 동일 네트워크 상에서 중복된 IP 주소를 사용하지 마십시오.



(2) 통신 옵션 설정

■ [메인 화면 > 제어판 > PLC]



항 목	설 정	비고
인터페이스	"Ethernet"을 선택합니다.	<u>"2. 외부 장치</u>
프로토콜	"High Speed Ethernet Server"을 선택합니다.	<u>선택" 참고</u>
IP	외부 장치의 IP 주소를 입력 합니다.	
Ethernet Protocol	TOP - 외부 장치 간 이더넷 프로토콜을 선택합니다.	
Port	외부 장치의 이더넷 통신 포트 번호를 입력합니다.	
TimeOut (ms)	TOP가 외부 장치로부터 응답을 기다리는 시간을 설정합니다.	
SendWait (ms)	TOP가 외부 장치로부터 응답 수신 후 다음 명령어 요청 전송 간에 대기 시간을	
	설정합니다.	



3.3 통신 진단

- TOP 외부 장치 간 인터페이스 설정 상태를 확인
- TOP 화면 상단을 터치하여 아래로 <u>드래그</u>. 팝업 창의 "EXIT"를 터치하여 메인 화면으로 이동한다
- -[제어판 > 이더넷] 에서 사용 하고자 하는 ETH 포트 설정이 외부 장치의 설정 내용과 같은지 확인한다

■ 포트 통신 이상 유무 진단

- [제어판 > PLC] 에서 "통신 진단"을 터치한다.
- 화면 상에 Diagnostics 다이얼로그 박스가 팝업 되며 진단 상태를 판단한다.

ОК	통신 설정 정상
Time Out Error	통신 설정 비정상
	- 케이블 및 TOP, 외부 장치의 설정 상태 확인한다. (참조 : 통신 진단 시트)

■ 통신 진단 시트

- 외부 단말기와 통신 연결에 문제가 있을 경우 아래 시트의 설정 내용을 확인 바랍니다.

항목	내용		확	·인	참 고
시스템 구성	시스템 연결 방법		OK	NG	1 시스템 그서
	접속 케이블 명칭	OK	NG	<u>1. 시스템 구성</u>	
TOP	버전 정보		OK	NG	
	사용 포트		OK	NG	
	드라이버 명칭		OK	NG	
	기타 세부 설정 사항		OK	NG	2 이번 자치 서태
	상대 국번	프로젝트 설정	OK	NG	2. 외부 장치 선택 3. 통신 설정
		통신 진단	OK	NG	<u>3. 중인 글장</u>
	이더넷 포트 설정	IP 주소	OK	NG	
		서브넷 마스크	OK	NG	
		게이트 웨이	OK	NG	
외부 장치	CPU 명칭	OK	NG		
	통신 포트 명칭(모듈 당	OK	NG		
	프로토콜(모드)	OK	NG		
	설정 국번	OK	NG	4. 외부 장치 설정	
	기타 세부 설정 사항		OK	NG	4. 되구 6시 26
	이더넷 포트 설정	IP 주소	OK	NG	
		서브넷 마스크	OK	NG	
		게이트 웨이	OK	NG	
	어드레스 범위 확인				5. 지원 어드레스
			OK	NG	(자세한 내용은 PLC 제조사의 매뉴얼을
					참고 하시기 바랍니다.)



4. 외부 장치 설정

"브라우저"를 사용하여 아래와 같이 설정 하십시오. 본 예제에서 설명된 내용보다 더 자세한 설정 법은 PLC 사용자 매뉴얼을 참조하십시오.



동일 네트워크 상에서 중복된 IP 주소를 사용하지 마십시오.

(2) 외부 장치 설정

"YASKAWA MOTOMAN "을 사용하여 아래와 같이 설정 하십시오. 본 예제에서 설명된 내용보다 더 자세한 설정법은 YASKAWA 사용자 매뉴얼을 참조하십시오.

설정된 IP는 아래와 같은 방법으로 확인하시기 바랍니다.

- "SECURIY" 모드에서 "management mode"로 변경합니다.
- 메인 메뉴에서 [SYSTEM INFO] -> [NETWORK SERVICE]를 눌러 network 설정을 확인합니다.




5. 지원 어드레스

TOP에서 사용 가능한 디바이스는 아래와 같습니다.

CPU 모듈 시리즈/타입에 따라 디바이스 범위(어드레스) 차이가 있을 수 있습니다. TOP 시리즈는 외부 장치 시리즈가 사용하는 최대 어드레스 범위를 지원합니다. 사용하고자 하는 장치가 지원하는 어드레스 범위를 벗어 나지 않도록 각 CPU 모듈 사용자 매뉴얼을 참조/주의 하십시오.

■ 디바이스 및 어드레스 기본 체계



Device	Class	Instance	Attribute	R/W	Remarks
Alarm	0x0070	1: The latest alarm	1: Alarm code	R	
		2: The second alarm from the	2: Alarm data		
		latest	3: By alarm type		
		3: The third alarm from the latest	4: Alarm occurring time		
		4: The fourth alarm from the	5: Alarm character string name		
		latest			
Alarm History	0x0071	1~100 : Major failure	1: Alarm code	R	
		1001~1100: Monitor alarm	2: Alarm data		
		2001~2100: User alarm (system)	3: Alarm type		
		3001~3100: User alarm (user)	4: Alarm occurring time		
		4001~4100: OFF line alarm	5: Alarm character strings name		
Status	0x0072	Fixed to '1'	1: Data 1	R	
			2: Data 2		
Job information	0x0073	1: Master task	1: Job name	R	
		2: Sub task 1	2: Line number		
		3: Sub task 2	3: Step number		
		4: Sub task 3	4: Speed override value		
		5: Sub task 4			
		6: Sub task 5			
		7: Sub task 6			
		8: Sub task 7			
		9: Sub task 8			
		10: Sub task 9			
		11: Sub task 10			
		12: Sub task 11			
		13: Sub task 12			
		14: Sub task 13			
		15: Sub task 14			
		16: Sub task 15			
Axis composition	0x0074	1 : R1~8 : R8Robot (pulse	1: "Axis name" of the first axis	R	
		value)	2: "Axis name" of the second axis		
		11 : B1~18 : B8Base (pulse	3: "Axis name" of the third axis		
		value)	4: "Axis name" of the fourth axis		
		21 : S1~44 : S24Station (pulse	5: "Axis name" of the fifth axis		
		value)	6: "Axis name" of the sixth axis		
		101 : R1~108 : R8Robot	7: "Axis name" of the seventh axis		
		(cartesian coordinate)	8: "Axis name" of the eighth axis		
		111 : B1~118 : B8Base			



		(cartesian coordinate)			
Robot Position	0x0075	1 : R1~8 : R8 Robot (pulse	1: Data type	R	
		value)	2: Form		
		11 : B1~18 : B8 Base (pulse	3: Tool number		
		value)	4: User coordinate number		
		21 : S1~44 : S24 Station (pulse	5: Extended form		
		value)	6: First axis data		
		101 : R1~108 : R8 Robot	7: Second axis data		
		(cartesian coordinate	8: Third axis data		
		(cartesian coordinate	9: Fourth axis data		
			10: Fifth axis data		
			11: Sixth axis data		
			11. Sixtif axis data		
			13: Eighth axis data		
Each axis positional	0x0076	1 : R1~8 : R8 Robot axis	1: First axis data	R	
deflection		11 : B1~18 : B8 Base axis	2: Second axis data		
		21 : S1~44 : S24 Station axis	3: Third axis data		
			4: Fourth axis data		
			5: Fifth axis data		
			6: Sixth axis data		
			7: Seventh axis data		
			8: Eighth axis data		
Each shaft torque	0x0077	1 : R1~8 : R8 Robot axis	1: First axis data	R	
·		11 : B1~18 : B8 Base axis	2: Second axis data		
		21 : S1~44 : S24 Station axis	3: Third axis data		
			4: Fourth axis data		
			5: Fifth axis data		
			6: Sixth axis data		
			7: Seventh axis data		
10.0	0.70	1.512.51	8: Eighth axis data	D 04/	
IO Data	0x78	• 1~512 : Robot user input signal	Fixed to "1".	R/W	
		• 1001~1512: Robot user output			
		signal			
		• 2001~2512: External input			
		signal			
		• 2701~2956: Network input			
		signal			
		• 3001~3512: External output			
		signal			
		• 3701~3956: Network output			
		signal			
IO Data(Multi)	0x300	• 4001~4160: Robot system input	Fixed to "0".	R/W	
•		signal			
		• 5001~5300: Robot system			
		output signal			
		• 6001~6064: Interface panel			
		input signal			
		• 7001~7999: Auxiliary relay			
		signal			
		8001~8128: Robot control status signal			
		status signal			
		• 8201~8220: Pseudo input			
		signal			
Register data	0x79	0~ 999 (writable register: 0 ~559)	Fixed to "1".	R/W	
Register data(Multi)	0x301		Fixed to "0".	R/W	
	·			_	



			100	ch Operation Panel
В	0x7A	0~99 (for standard setting)	Fixed to "1".	R/W
B(Multi)	0x302		Fixed to "0".	R/W
I	0x7B	0~99 (for standard setting)	Fixed to "1".	R/W
I(Multi)	0x303		Fixed to "0".	R/W
D	0x7C	0~99 (for standard setting)	Fixed to "1".	R/W
D(Multi)	0x304		Fixed to "0".	R/W
R	0x7D	0~99 (for standard setting)	Fixed to "1".	R/W
R(Multi)	0x305		Fixed to "0".	R/W
S 16 byte	0x7E	0~99 (for standard setting)	Fixed to "1".	R/W
S 16 byte(Multi)	0x306		Fixed to "0".	R/W
Р	0x7F	0~127 (for standard setting)	1: Data type	R/W
			2: Form	
			3: Tool number	
			4: User coordinate number	
			5: Extended form	
			6: "Coordinated data" of the first	
			axis	
			7: "Coordinated data" of the	
			second axis	
			8: "Coordinated data" of the third	
			axis	
			9: "Coordinated data" of the	
			fourth axis	
			10: "Coordinated data" of the	
			fifth axis	
			11: "Coordinated data" of the	
			sixth axis	
			12: "Coordinated data" of the	
			seventh axis	
			13: "Coordinated data" of the	
D(A 4 1/2)	0.207	-	eighth axis	D 044
P(Multi)	0x307	0. 127 (for stondondondon)	Fixed to "0".	R/W
BP	0x80	0~127 (for standard setting)	1: Data type 2: "Coordinated data" of the first	R/W
			axis	
			3: "Coordinated data" of the	
			second axis	
			4: "Coordinated data" of the third	
			axis	
			5: "Coordinated data" of the	
			fourth axis	
			6: "Coordinated data" of the fifth	
			axis	
			7: "Coordinated data" of the sixth	
			axis	
			8: "Coordinated data" of the	
			seventh axis	
			9: "Coordinated data" of the	
]	eighth axis	
BP(Multi)	0x308		Fixed to "0".	R/W
EX	0x81	0~127 (for standard setting)	1: Data type	R/W
			2: "Coordinated data" of the first	
			axis	
			3: "Coordinated data" of the	
			second axis	
· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	



			1000	ch Operation	Fallel
			4: "Coordinated data" of the third		
			axis		
			5: "Coordinated data" of the		
			fourth axis		
			6: "Coordinated data" of the fifth		
			axis		
			7: "Coordinated data" of the sixth		
			axis		
			8: "Coordinated data" of the		
			seventh axis		
			9: "Coordinated data" of the		
			eighth axis		
EX(Multi)	0x309		Fixed to "0".	R/W	
Alarm (detailed)	0x30A	1: The latest alarm	1: Alarm code	R	
, ,		2: The second alarm from the	2: Alarm data		
		latest	3: By alarm type		
		3: The third alarm from the latest	4: Alarm occurring time		
		4: The fourth alarm from the	5: Alarm character string name		
		latest	6: Sub code data additional		
			information character strings		
			7:Sub code data character strings		
			8:Sub code data character strings		
Alama histam (alatailad)	0200	1 100 · Maio » fail	reverse display information 1:Alarm code	n	
Alarm history (detailed)	0x30B	1~100 : Major failure		R	
		1001~1100: Monitor alarm	2:Alarm data		
		2001~2100: User alarm (system)	3:Alarm type		
		3001~3100: User alarm (user)	4:Alarm occurring time		
		4001~4100: OFF line alarm	5:Alarm character strings name		
			6:Sub code data additional		
			information character strings		
			7:Sub code data character strings		
			8:Sub code data character strings		
			reverse display information		
Reset cancellation	0x0082	1: Resetting of alarm	Fixed to "1".	W	
		2: Cancelling of error			
On/off	0x0083	1: HOLD	Fixed to "1".	W	
		2: Servo ON			
		3: HLOCK			
Start switch	0x0084	2: CYCLE (switching of	Fixed to "1".	W	
		STEP/CYCLE/CONTINUE)			
Sting display to pendant	0x0085	Fixed to "1".	Fixed to "1".	W	
Start	0x0086	Fixed to "1".	Fixed to "1".	W	
Job select	0x0087	1: Set the executing job	1: Job name	W	
		10: Set the master job (task 0)	2: Line number (valid only when		
		11: Set the master job (task 1)	executing job setting.)		
		12: Set the master job (task 2)			
		13: Set the master job (task 3)			
		14: Set the master job (task 4)			
		15: Set the master job (task 5)			
		•			
		16: Set the master job (task 6)			
		17: Set the master job (task 7)			
		18: Set the master job (task 8)			
		19: Set the master job (task 9)			
		20: Set the master job (task 10)			
	1	21: Set the master job (task 11)			1



			To To	ouch Operation	Panel
		22: Set the master job (task 12)			
		23: Set the master job (task 13)			
		24: Set the master job (task 14)			
		25: Set the master job (task 15)			
Administration Hour	0x0088	1 :Control power ON time	1: Operation start time	R	
		10 :Servo power ON time (TOTAL)	2: Elapse time		
		11~18 :Servo power ON time (R1			
		to R8)			
		21~ 44 :Servo power ON time			
		(S1~S24)			
		110 :Play back time (TOTAL)			
		111~118 :Play back time (R1~			
		R8)			
		121~144 :Play back time			
		(S1~S24)			
		210 :Motion time (TOTAL)			
		211~218 :Motion time (R1~R8)			
		221~244 :Motion time (S1~S24)			
		301~308 :Operation time			
		(application 1~ 8)			
System information	0x0089	11~18: Type information (R1~R8)	1: System software version	R	
		21~44: Type information (S1~24)	2: Model name / application		
		101~108: Application information	3: Parameter version		
		(application 1~8)			
S 32 byte	0x8E	0~99 (for standard setting)	Fixed to "1".	R/W	
S 32 byte(Multi)	0x30C		Fixed to "0".	R/W	